

## **Mahasarakam Hospital in Thailand**

**I update my situation 20/11/2019.**

**Now I work with Dr.Thammason for make a national research this research will be published in Asean journal in English language I can share it for you when finish. ( expected to finish it in 3 months)**

**And last month I have tested Wellis in Mahasarakam Hospital the result is great but the result is confidential for hospital I can't send to you in full copy but I can show you some page.**

**They tested 3 different ICU in Mahasarakam Hospital in Thailand**

**Surgical ICU**

**Medical ICU**

**Pediatric ICU**

**In isolation room 30 sq.m./ 1 x WADU-02 per room of each ICU ( before and after WADU-02 installation)**

**Test in total pathogen**

**Test with air borne ( passive air sampling ) and surface scrub method the result is great**




**Tested by Australian pathogen testing company.**

**See the following test results, we once more surprise about our great performance : first one is before and next below one is after ( "Note After wellis" MARKED)**









**GREEN & HEALTHY AUDITORS PTY LTD**

ABN 34532464300  
 50 Darling Point Rd, Darling Point, NSW 2027 Australia  
 Ph + 614149469 F =61293621010 Email [asava@hotmail.com](mailto:asava@hotmail.com)

| MICROBIAL |  |                    |  |   |
|-----------|--|--------------------|--|---|
| Alert?    | Contaminant  | Result             | Location   | % Of Reduction  |
| *         | Sample:P01<br>Passive air Sample2<br>hours<br>Table bedside<br>                                     | 27 cfu /4<br>hours |    |  |
|           | Sample:P01-2<br>Passive air Sample2<br>hours<br>Table bedside<br>Note After wellis<br>             | 11 cfu /4<br>hours |  | 56 % Reduction  |
| *         | Sample:P02<br>Passive air Sample2<br>hours<br>Above old air purifier<br>                          | 43 cfu /4<br>hours |  |   |
|           | Sample:P02-2<br>Passive air Sample2<br>hours<br>Above old air purifier<br>Note : After wellis<br> | ~8 cfu/4<br>hours  |  | 80 % Reduction  |










**GREEN & HEALTHY AUDITORS PTY LTD**

ABN 34532464300  
 50 Darling Point Rd, Darling Point, NSW 2027 Australia  
 Ph + 614149469 F =61293621010 Email [gsava@hotmail.com](mailto:gsava@hotmail.com)

| MICROBIAL |   |                    |  |                |
|-----------|---|--------------------|--|----------------|
| Alert?    | Contaminant   | Result             | Location   | % Of Reduction |
|           | Sample:P03<br>Passive air Sample2<br>hours<br>Table cart<br>                                   | 24 cfu /4 hours    |    |                |
|           | Sample:P03-2<br>Passive air Sample2<br>hours<br>Top of the cart<br>Note : After wellis<br>    | 12 cfu /4 hours    |  | 50 % Reduction |
| *         | Sample:S01<br>Surface swab<br>Right side of the<br>Remote control<br>                        | 580 cfu /100 sq cm |  |                |
|           | Sample:S01-2<br>Surface swab<br>Left side of the bed<br>control 5<br>Note : After wellis<br> | 170 cfu /100 sq cm |  | 70 % Reduction |

**GREEN & HEALTHY AUDITORS PTY LTD**

ABN 34532464300  
 50 Darling Point Rd, Darling Point, NSW 2027 Australia  
 Ph + 614149469 F =61293621010 Email [gsava@hotmail.com](mailto:gsava@hotmail.com)

| MICROBIAL |  |                   |  |   |
|-----------|--|-------------------|--|---|
| Alert?    | Contaminant  | Result            | Location   | % Of Reduction  |
|           | Sample:S02<br>Surface swab<br>Drip controller<br>                           | 20 cfu /100 sq cm |    |  |
|           | Sample:S02-2<br>Surface swab<br>Drip controller<br>Note : After wellis<br> | 0 cfu /100 sq cm  |   | 100%Reduction   |
|           | Sample:S03<br>Surface swab<br>Table bedside<br>                           | 70 cfu/100sq cm   |  |   |
|           | Sample:S03-2<br>Surface swab<br>Table bedside<br>Note : After wellis<br>  | 0 cfu /100 sq cm  |  | 100 %Reduction  |

**GREEN & HEALTHY AUDITORS PTY LTD**

ABN 34532464300  
 50 Darling Point Rd, Darling Point, NSW 2027 Australia  
 Ph + 614149469 F =61293621010 Email [gsava@hotmail.com](mailto:gsava@hotmail.com)

| MICROBIAL |  |                           |  |                |
|-----------|--|---------------------------|--|----------------|
| Alert?    | Contaminant  | Result                    | Location   | % Of Reduction |
| ***       | Sample:S04<br>Surface swab<br>Supply air grill<br>                            | >30,000 cfu<br>/100 sq cm |  |                |
| ***       | Sample:S04<br>Fungi & Yeast<br>Supply air grill<br>                          | >30,000 cfu<br>/100 sq cm |  |                |
|           | Sample:S04-2<br>Surface swab<br>Supply air grill<br>Note : After wellis<br> | >10,000 cfu<br>/100 sq cm |  | 66%Reduction   |